

ANC24LA033

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of accident airplane at accident site (Courtesy of AST)



Photograph 2 - Side view of accident airplane at accident site (Courtesy of AST)



Photograph 3 - Rear view of accident airplane at accident site (Courtesy of AST)