

ANC24LA034

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of left wing, fuselage, and empennage (Courtesy of Cashe County Sheriff)



Photograph 2 - Image of fuselage, left wing, and empennage (Courtesy of Cashe County Sheriff)



Photograph 3 - Image of empennage (Courtesy of Cashe County Sheriff)