

ANC24LA039

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of top of accident helicopter and rotors (Courtesy of FAA)



Photograph 2 - View of accident helicopter tail and bottom section (Courtesy of FAA)



Photograph 3 - View of accident helicopter tail boom and rotor and fuselage (Courtesy of FAA)



Photograph 4 - View of front of accident helicopter (Courtesy of FAA)