

ANC24LA040

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of wings, fuselage, and left horizontal stabilizer (Courtesy of Pilot)



**Photograph 2 - Image of right wing, right horizontal stabilizer, vertical stabilizer, and fuselage
(Courtesy of Pilot)**