

[ANC24LA042]

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Front view of accident airplane**



**Photograph 2 - Damage to left wing tip**



**Photograph 3 - Damage to left elevator**



**Photograph 4 - Image of ground track marks of accident aircraft**