

ANC24LA048

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane on the runway (Courtesy of pilot)



Photograph 2 - View of the damage to the fuselage.



Photograph 3 - View of damage to the bottom of the fuselage.