

ANC24LA050

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of Fuselage, right wing, and empennage (Courtesy of Operator)



Photograph 2 - Image of left wing and left aileron (Courtesy of Operator)



Photograph 3 - Image of lower aft fuselage, empennage, and tailwheel (Courtesy of Operator)