

ANC24LA071

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of Glider Right Wing (Courtesy of Pilot)



Photograph 2 - View of Wing Section that was liberated from glider (Courtesy of Pilot)