


ANC24LA074

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left Wing of Accident Airplane (Courtesy of Fairbanks Airport Operations)



Photograph 2 - Impact mark on runway (Courtesy of Fairbanks Airport Operations)