

ANC24LA076

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane at accident site (Courtesy of owner)



Photograph 2 -Right side of the accident airplane at the accident site. (Courtesy of owner)



Photograph 3 - View of the underside of the right wing (Courtesy of owner)



Photograph 4 - View of right side of the accident airplane (Courtesy of owner)



Photograph 5 - View of right wing strut. (Courtesy of owner)