

ANC24LA079

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident helicopter at accident site (Courtesy of passenger)



Photograph 2 - View of accident helicopter at accident site (Courtesy of passenger)



Photograph 5 - Front view of accident helicopter at accident site (Courtesy of passenger)



Photograph 6 - View of accident helicopter at accident site (Courtesy of passenger)