

ANC24LA082

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane where it came to rest. (Courtesy of pilot)



Photograph 2 - View of the airplane and the separated landing gear. (Courtesy of pilot)



Photograph 3 - View of separated left main landing gear.