

ANC24LA097

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aft view of accident airplane at accident site. (Courtesy of owner)



Photograph 2 - Left wing damage on accident airplane (Courtesy of owner)



Photograph 3 - Left side of accident airplane at accident site (Courtesy of owner)