

ANC24LA098

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane from behind (Courtesy of Owner)



Photograph 2 - View of left wing (Courtesy of Owner)



Photograph 3 - View of accident airplane left wing (Courtesy of Owner)



Photograph 4 - Accident airplane landing gear (Courtesy of Owner)