

ANC24LA103

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane where it came to rest (Courtesy of pilot)



Photograph 2 - View of damage to the left wing (Courtesy of pilot)