

ANC25LA017


INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane on its nose



Photograph 2 - View of damage to fuselage of airplane



Photograph 3 - Fuel gauges at accident site