

ANC25LA021

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane after recovery (Courtesy of the FAA)



Photograph 2 - Damage to the right wing (Courtesy of the FAA)



Photograph 3 - Damage to the right wing (Courtesy of the FAA)