

ANC25LA032

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane after recovery (Courtesy of FAA)



Photograph 2 - Accident airplane after recovery (Courtesy of FAA)



Photograph 3 - View of damage to upper windshield area (Courtesy of FAA)