

ANC25LA053

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane at accident site (Courtesy of Owner)



Photograph 2 - View of accident airplane at accident site (Courtesy of Owner)



Photograph 3 - View of accident airplane at accident site (Courtesy of Owner)