

ANC25LA090

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane where it came to rest inverted. (Courtesy of operator)



Photograph 2 - View of airplane nose to tail (Courtesy of operator)