

ANC25LA095

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane at accident site (Courtesy of Operator)



Photograph 2 - Image of fuselage and right main landing gear (Courtesy of Operator)