

ANC25LA096

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of right side of airplane where it came to rest. (Courtesy of Alaska State Troopers)



Photograph 2 - View of the forward section of the airplane (Courtesy of Alaska State Troopers)



Photograph 3 - View of damage to the bottom of the fuselage (Courtesy of Federal Aviation Administration)