



Photo 1 – Airplane in yard, viewed from right side, nose gear collapsed



Photo 2 – Airplane viewed from front, nose gear collapsed, both wings damaged