

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: CEN14LA159
--	---------------------------------------

For Use In All Modal Investigations

OFFICE Aviation Safety	DATE OF ACCIDENT 3/8/14	ACCIDENT LOCATION (City & State) Wapakoneta, OH
EVIDENCE OBTAINED BY:		
☒ EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION On-scene	DATE 4/10/14
☐ EVIDENCE RECEIVED FROM:		
EVIDENCE CONTROL NUMBER CEN14LA159 - IIC - 01		GROUP IIC
DESCRIPTION (☐ BIN ITEM - HAS BEEN SEPARATED ☐ Southwind heater unit, model 8240-E, part no: 072208		

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Steven	LAST NAME: Sprague
ADDRESS:	
PHONE:	EMAIL:
RETURNED ☐	DATE:
CONTACT:	

CHAIN OF CUSTODY

RELEASED BY: IIC	RELEASED TO: RE-30	DATE:
PURPOSE: Examine and pressure test Southwind heater unit., UPS Tracking No.: 1Z3F1W060311425813 & 1Z3F1W060311425911		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		