

#1
CORROSION
←



Photo 3 - Corroded Flight Control Rod Bearing