



Photo 1 – Dubuque Regional Airport and Accident Site




Photo 2 – Aerial Photo of the Accident Site



Photo 3 – Initial Impact with Trees



Photo 4 – Impact Ground Scar



Photo 5 – Ground Scar



Photo 6 – Debris Field



Photo 7 – Airplane Debris



Photo 8 – Airplane Main Wreckage



Photo 9 – Main Wreckage, Aft View



Photo 10 – Main Wreckage, Left Side View



Photo 11 – Main Wreckage, Forward View



Photo 12 – Right Outboard Wing



Photo 13 - Engine



Photo 14 – Propeller Blade Tip



Photo 15 – Cut Tree Branch