



Photo 1 – Photo of main wreckage and trees surrounding the area



Photo 2 - Photo of main wreckage and trees surrounding the area



Photo 3 - Photo of main wreckage and trees surrounding the area



Photo 4 - Photo of main wreckage



Photo 5 - Photo of trees in the immediate area of the accident site



Photo 6 - Photo of gyroscopic instrument cage



Photo 7 - Photo of wreckage layout during post-scene examination



Photo 8 - Photo of wreckage layout during post-scene examination



Photo 9 - Photo of wreckage layout during post-scene examination



Photo 10 – Photo of right engine during post-scene examination



Photo 11 – Photo of left engine during post-scene examination