



Photo 1 – View of Main Wreckage.



Photo 2 – View of main Wreckage from Tail Section Looking Forward.



Photo 3 – Right Wingtip.



Photo 4 – View of Impact Mark from Trees on Right Wingtip.



Photo 5 – Left Wingtip.



Photo 6 – Propeller Blades and Hub.




Photo 7 – View of Emergency Locator Transmitter Connected within Airplane in “OFF” Position.