



Photo 1 – View of the burned wreckage in a field



Photo 2 – View of the wreckage from the front right side of the airplane



Photo 3 – View of burned wings, cabin, and fuselage



Photo 4 – View of damage to the outboard section of the left wing



Photo 5 – View of burned engine compartment, cabin, and fuselage



Photo 6 – View of fire consumed cockpit



Photo 7 – View of engine and propeller



Photo 8 – View of propeller flange



Photo 9 – View of propeller flange and cylinders



Photo 10 – View of fire damaged propeller



Photo 11 – View of bent and twisted propeller blade



Photo 12 – View of crankshaft and piston rods



Photo 13 – Aerial view of water leak near crash site




Photo 14 – Overhead aerial view of water leak near crash site



Photo 15 – Ground view of water leak near accident site