



Photo 1 – Preaccident photo of N564ER – photo is timestamped 2-11-2015 at 1345 MST (Brian Rosin Photo)



Photo 2 – Initial impact ground scars at the accident scene – viewer looking southeast (NTSB Photo)



Photo 3 – Wreckage debris – viewer looking northwest (NTSB Photo)



Photo 4 – Partially buried propeller – in situ (NTSB Photo)



Photo 5 – Propeller – after recovery (NTSB Photo)



Photo 6 – Propeller – showing fracture surfaces on the propeller flange (NTSB Photo)



Photo 7 – Completely separated forward fuselage and engine – viewer looking east (NTSB Photo)



Photo 8 – Completely separated tail surfaces – viewer looking northeast (NTSB Photo)