



Photo 1 – Accident site



Photo 2 - Brake cylinder



Photo 3 - Wreckage - part of rudder pedals

Cessna Photo



Photo 4 - Rudder cable attachment



Photo 5 - Rudder attachment



Photo 6 - Rudder




Photo 7 - Engine

Lycoming photo



Photo 8 - Damaged propeller



Shoe: Similar to the ones
the pilot was wearing.

Photo 9 - Pilot's shoe and example shoe



Photo 10 - Pieces of shoe and pedal



Photo 11 – Rudder pedal component