



Photo 1 – Aerial view of accident site and Runway 27



Photo 2 – Aerial view of Runway 27 with orange and green dots



Photo 3 – Aerial view of accident site and approach end of Runway 27



Photo 4 – View of initial impact on the runway



Photo 5 – View of the debris path



Photo 6 – Propeller slash marks on the runway



Photo 7 – Broken propeller blade with heavy damage



Photo 8 – View of debris path with fire discoloration on the runway



Photo 9 – View of separated right wing with impact and fire damage



Photo 10 – View of right side of the airplane with the right wing missing



Photo 11 – View of the left side of the airplane wreckage



Photo 12 – View of the airplane from the left rear quarter



Photo 13 – View of the empennage and right side of the airplane



Photo 14 – View of the crushing on the right side of the airplane's nose



Photo 15 – View of pilot's instrument panel




Photo 16 – View of the engine with the top cowling removed