



Photo 1 – Preaccident photo of N929DS (Owner Photo)



Photo 2 – Airplane wreckage as viewed from the southeast (NTSB Photo)



Photo 3 – View to the north from the wreckage location (NTSB Photo)



Photo 4 – View of the wreckage from the bottom of the ditch, looking southeast (NTSB Photo)



Photo 5 – Close-up view of the south sidewall of the concrete box culvert (NTSB Photo)



Photo 6 – Damaged propeller blade (NTSB Photo)