



Photo 1 – 367 foot tall cellular tower as viewed from the street, looking up (FAA Photo)



Photo 2 – Street level view of the base of cellular tower (FAA Photo)



Photo 3 – Top of 367 foot tall cellular tower – photo dated May, 2014 (Verizon Photo)



Photo 4 – View of separated lightning rod – photo dated December, 2014 (Verizon Photo)



Photo 5 – View of lightning rod support pipe brackets – photo dated December, 2014 (Verizon Photo)



Photo 6 – Impact damaged tree (FAA Photo)



Photo 7 – Wreckage as viewed from the airplane's left side (FAA Photo)



Photo 8 – Wreckage as viewed from the airplane's rear (FAA Photo)




Photo 9 – Damage to the propeller and the airplane's front section. (FAA Photo)