



Photo 1 – Accident Site



Photo 2 – Ice on Windscreen



Photo 3 – Ice on the Vertical Stabilizer



Photo 4 – Ice on the Vertical Stabilizer



Photo 5 – Top of Vertical Stabilizer and Rotating Beacon



Photo 6 – Ice on the Antennas



Photo 7 – Ice on Antenna



Photo 8 – Ice on Antenna



Photo 9 – Ice Found on Ground



Photo 10 – Left Horizontal Stabilizer



Photo 11 – Ice on Left Horizontal Stabilizer