



Photo 1 – A front view of the main wreckage.




Photo 2 – The separated carburetor heat sheath and clamp.