


Record of N2320U Partial Inspection

Name: Casey Storm, ASI
Location: Milstead Automotive, [REDACTED] Spring, TX 77386
Phone: [REDACTED]
Date/Time: July 8, 2015 0730 - 0900
Description: Partial Inspection of A/C Wreckage

I performed a partial inspection of the aircraft carburetor & gascolator at the request of Del Scott, IIC for this accident investigation. The aircraft was still inverted and on a trailer, so these items were easily accessed. The gascolator appeared to be intact and had a small amount of water in it. No debris was present. Carburetor appeared to be normal as well with no water, corrosion or debris present. The associated fuel lines that could be seen appeared to be intact as well. I did see quite a bit of oil and dirt on the air intake filter and the rest of the engine compartment as well. Several pictures were taken and downloaded to Inspector Scott's computer for his review and disposition.



C. Storm
Aviation Safety Inspector