

Solano Aircraft Maintenance LLC
3473 Airport Drive #1
Torrance, CA 90505
(562) 331-1116
solanoaircraft@yahoo.com

N477TC 1/12/2016 TTAF: 431.5 HOBBS: 431.5

Annual Inspection - Aircraft

Annual inspection was completed on this aircraft, Cirrus 2003 SR20 S/N 1378. The following was also accomplished. Lubricated all hinges, bearings, pulleys, greased wheel bearing, replaced airfilter BA24, cleaned fuel screens, checked all lights OK. Tested ELT battery per FAR 91.207(D) next due 1/2017. Replaced nose gear pucks p/n 13389-001

I certify this AIRCRAFT has been inspected in accordance with an Annual Inspection and found to be airworthy. All ADs checked through 2015-25.

Thomas R. Shaw
A&P [REDACTED] IA

Solano Aircraft Maintenance LLC
3473 Airport Drive #1
Torrance, CA 90505
(562) 331-1116
solanoaircraft@yahoo.com

N477TC 1/12/2016 TTAF: 431.5 TSN: 431.5

Annual Inspection - Engine

Compression Check 1) 77/80 2) 78/80 3) 76/80 4) 77/80 5) 78/80 6) 78/80. Cleaned and gapped sparkplugs, checked mag timing- operational check- OK. Cleaned fuel injectors. Test run engine, checked for leaks OK. Repaired cover for airfilter.

I certify this ENGINE has been inspected in accordance with an Annual Inspection and found to be airworthy. All ADs checked through 2015-25.

Thomas R. Shaw
A&P [REDACTED] A


Solano Aircraft Maintenance LLC
3473 Airport Drive #1
Torrance, CA 90505
(562) 331-1116
solanoaircraft@yahoo.com
N477TC 1/12/2016 TTAF: 431.5 TSN: 431.5

Annual Inspection - Propeller

I certify this PROPELLER has been inspected in accordance with an Annual / 100 Hour Inspection and found to be airworthy. All ADs checked through 2015-25.

Thomas R. Shaw
A&P [REDACTED] IA

MAKE: Cirrus
MODEL: SR20
S/N: 1378
REG. NO: 47TTC
WORK ORDER: 18263



Kim Davidson Aviation, Inc.
Repair Station No. YYKR678L
2701 Airport Avenue
Santa Monica, CA 90405
Phone: (Maint 310-391-6283) (Avionics 310-391-0692)

DATE: 1/7/2016
A/C TSN: 431.6
HOBBS: 431.6

Airframe Entries

CW 6yr Replacement of CAPS Line Cutters w/new IAW Cirrus Maintenance Manual. Installed CAPS Line Cutters s/n 8784 and s/n 8750. CAPS Line Cutters Next Due 11/2021

Maintenance Release

The aircraft, airframe, engine, propeller or appliance identified above was Repaired & Inspected in accordance with the current maintenance rules of the Federal Aviation Administration and is APPROVED FOR RETURN TO SERVICE.

DATE: 1/7/2016

SIGNED:

Work Order: 18263

Kim Davidson

Certified Repair Station No. [REDACTED]

Printed by EBis 3 (datamedia.com)