



Photo 1 – Airplane at accident site



Photo 2 – Engine exhaust muffler, view #1



Photo 3 – Engine exhaust muffler, view #2



Photo 4 – Engine exhaust muffler, view #3



Photo 5 – Engine exhaust shroud, view #1



Photo 6 – Engine exhaust shroud, view #2