



Photo 1 – View of the front of the airplane.



Photo 2 - View of the left side of the airplane.



Photo 3 - View of the rear side of the airplane.



Photo 4 - View of the right side of the airplane.



Photo 5 – View of the engine.



Photo 6 – View of the fuel strainer.



Photo 7 - FAA supplied photo of the fuel tank selector.



Photo 8 - View of the carburetor bowl.



06.09.2016 15:50

Photo 9 - View of the disassembled carburetor.



Photo 10 - View of the left fuel tank vent line.




Photo 11 - View of the disassembled fuel cap.



Photo 12 - View of the accident engine in the test cell.