



Photo 1 – Airplane at accident site



Photo 2 – Airplane after recovery from lake



Photo 3 – Left side of airplane



Photo 4 – Engine and propeller



Photo 5 – Instrument panel