



Photo 1 – Accident Overview (Textron Photo)



Photo 2 – Accident Overview 2 (Textron Photo)



Photo 3 – Left Propeller at Scene



Photo 4 – Left Propeller (Textron Photo)



Photo 5 – Right Engine and Propeller (Textron Photo)



Photo 6 – Right Propeller Broken Blade



Photo 7 – Airspeed Indicator



Photo 8 – Fuel Selectors




Photo 9 – Profile at Aero Club (Photo provided by USAF)