



**Photo 1 – Air boat en route to the accident site.**



**Photo 2 - Terrain surrounding the accident site.**



**Photo 3 - View from the accident site looking straight up at the hole in the tree canopy.**



**Photo 4 - The partially submerged wreckage.**



**Photo 5 - The tail boom.**



**Photo 6 - Blade contact mark.**



**Photo 7 – Preparing for airframe examination.**



**Photo 8 – Preparing for engine examination.**



**Photo 9 - Accident helicopter instrument panel.**



**Photo 10 - Exemplar helicopter instrument panel.**