



Photo 1 – View of the wreckage from the front of the glider



Photo 2 – View of the wreckage from the left side of the glider



Photo 3 – View of the wreckage from the rear of the glider



Photo 4 – View of the empennage



Photo 5 – View of the broken right wing



Photo 6 – View of the broken sections of the right wing



Photo 7 – View of the cockpit



Photo 8 – View of the cockpit instruments



Photo 9 – View of the control stick and cockpit controls



Photo 10 – View of the seat back adjustment holes in an exemplar glider



Photo 11 – View of seat back reclining adjustments in an exemplar glider



Photo 12 – View of exemplar pilot sitting in an exemplar glider