



Photo 1 – Overhead view of accident #1



Photo 2 – Overhead view of accident site #2



Photo 3 – Accident site viewed from side of left wing



Photo 4 – Accident site from front of aircraft




Photo 5 – Engine at recovery site