



Photo 1 – Airplane wreckage as viewed from the right rear (FAA Photo)



Photo 2 – Airplane wreckage as viewed from the left (FAA Photo)



Photo 3 – Damage to overhead trees as viewed from the wreckage location (FAA Photo)



Photo 4 – View of engine cowling, propeller, and propeller spinner (FAA Photo)