




Photo 1 – Airplane Wreckage at Accident Site



Photo 2 – Engine at Examination Facility



Photo 3 – Carburetor Bowl with Water Contamination



Photo 4 – Carburetor Bowl with Corrosion