



Photo 1 – Accident Airplane, N88FL



Photo 2 – Accident Airplane, Front View



Photo 3 – Accident Airplane, Right Side View



Photo 4 – Accident Airplane, Rear View



Photo 5 – Accident Airplane, Left Side View



Photo 6 – Forward Fuselage and Nose Gear



Photo 7 – Right Wing Damage



Photo 8 – Left Main Landing Gear



Photo 9 – Parallel Taxiway



Photo 10 – Taxiway, Perimeter Road, and the Airplane



Photo 11 – Tire Marks



Photo 12 – Casey Municipal Airport



Photo 13 – Overhead Photo of Casey Municipal Airport



Photo 14 – Casey Municipal Airport, Parallel Taxiway and Perimeter Road