

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Shiprock State: NM

ZIP: 86515 Country: USA

Latitude: 36-41-50.1000N Longitude: 108-42-04.7000W

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: March 31, 2016 Local Time: 11:35
mm/dd/yyyy

Time Zone: Mountain Time

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N180XV

Manufacturer: Cessna

Model: 180D

Serial Number: 18050998

Year of Manufacture: 1961

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

☒ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 2650 lbs

Weight at Time of Accident/Incident: 2369 lbs

Number of Seats: 4 Flight Crew Seats: 0

Cabin Crew Seats: 1 Passenger Seats: 3

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
- ☐ Balloon
- ☐ Blimp/Dirigible
- ☐ Glider
- ☐ Gyroplane
- ☐ Helicopter
- ☐ Powered Lift
- ☐ Rocket
- ☐ Ultralight
- ☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
- ☐ Aerobatic
- ☐ Balloon
- ☐ Commuter
- ☐ Transport
- ☐ Utility

Special

- ☐ Restricted
- ☐ Limited
- ☐ Provisional
- ☐ Special Flight
- ☐ Experimental
- ☐ Special Light-Sport
- ☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☐ Tricycle ☒ Tailwheel
- ☐ Amphibian ☐ High Skid
- ☐ Emergency Float ☐ Skid
- ☐ Float ☐ Ski
- ☐ Hull ☐ Ski/Wheel
- ☐ Other Launch/Recovery System
- ☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
- ☐ Turbo Shaft ☐ Solid Rocket
- ☐ Turbo Prop ☐ Hybrid Rocket
- ☐ Turbo Jet ☐ None
- ☐ Turbo Fan ☐ Unknown
- ☐ Electric

Fuel System Type (Reciprocating)

- ☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	<u>Continental</u>	<u>O-470R</u>	<u>901199-0H</u>		<u>230</u>	<u>5221</u>	<u>5</u>	<u>1359</u>
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
- ☐ AAIP ☐ Conditional Inspection
- ☒ Annual ☐ Unknown

Date Last Inspection: 12/23/2015
mm/dd/yyyy

Airframe Total Time: 5308.5 hrs

hours measured at (Select one)

☒ Last Inspection ☐ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
- ☐ Conditional (Amateur-built only)
- ☐ Manufacturer's Inspection Program
- ☐ Other Approved Inspection Program (AAIP)
- ☐ Continuous Airworthiness
- ☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
- ☐ Specify: _____

Propeller 1

- ☐ Fixed Pitch
- ☒ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: McCauley

Model: 3 bladed constant speed 180

Propeller 2

- ☐ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: ARTEX

Model or Part No.: _____

TSO No.: ☐ OC91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☐ OC126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☒ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☒ No

If not activated:

- Indicate Reason:
- ☐ Impact Damage
 - ☐ Fire Damage
 - ☐ Battery Expired/Damaged
 - ☐ Unknown

Additional Equipment (Check all that apply)

- ☒ ADS-B
- ☐ Airframe Parachute
- ☐ Angle of Attack Indicator
- ☒ Autopilot
- ☐ Data Recorder
- ☒ Electronic Flight Bag or Handheld Device
- ☒ Electronic Multifunction Display
- ☐ Electronic Primary Flight Display
- ☐ Handheld GPS
- ☐ Heads Up Display
- ☒ Onboard Weather
- ☐ Satellite Tracking Device
- ☒ Stall Warning System
- ☐ Video Recording Device
- ☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: TumiAir, Inc.City: DurangoFractional Ownership Aircraft: ☐ Yes ☒ NoState: CO ZIP: 81301Country: USA**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____ ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☐ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: Shiprock

Distance From Airport Center: _____ sm

Airport Identifier: 5V5

Direction From Airport: _____ degrees true

Proximity to Airport: ☐ Off Airport/Airstrip ☒ On Airport/Airstrip ☐ N/AAirport Elevation: 5270 ft. msl**Runway Information**Runway ID: 20 (L/R/C) Length: 4840 ft Width: 75 ft**Runway/Landing Surface (Check all that apply)**

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☒ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☒ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☒ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Joseph City of Residence: Durango
 Middle Initial: F State: CO ZIP: 81301
 Last Name: Tumminaro Country: USA
 Age at time of Accident/Incident: 67 Date of Birth: mm/dd/yyyy
 Certificate Number:

Degree of Injury ☐ None ☐ Fatal ☐ Minor ☐ Unknown ☒ Serious	Seat Occupied ☐ Left ☐ Front ☐ Unknown ☒ Right ☐ Rear ☐ Center ☐ Single	Restraint Type <table style="width: 100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap only</td> <td>☐ Lap only</td> </tr> <tr> <td>☐ 3-point</td> <td>☐ 3-point</td> </tr> <tr> <td>☒ 4-point</td> <td>☒ 4-point</td> </tr> <tr> <td>☐ 5-point</td> <td>☐ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table>	Available	Used	☐ None	☐ None	☐ Lap only	☐ Lap only	☐ 3-point	☐ 3-point	☒ 4-point	☒ 4-point	☐ 5-point	☐ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Available	Used																
☐ None	☐ None																
☐ Lap only	☐ Lap only																
☐ 3-point	☐ 3-point																
☒ 4-point	☒ 4-point																
☐ 5-point	☐ 5-point																
☐ Unknown	☐ Unknown																
Pilot Certificate(s) (Check all that apply) ☐ None ☒ Flight Instructor ☒ Commercial ☐ US Military ☒ Private ☐ Recreational ☒ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer																	

Principal Occupation ☒ Pilot ☐ Other ☐ Unknown	Medical Certificate ☐ None ☐ Class 3 ☒ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown	Medical Certificate Validity ☐ Without limitations/waivers ☐ Unknown ☒ With limitations/waivers ☐ N/A ☐ Special Issuance	Date of Last Medical <u>04/21/2015</u> mm/dd/yyyy
---	---	---	--

Medical Certificate Limitations

must wear corrective lenses

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

August 29, 2014
mm/dd/yyyy

Flight Review Aircraft

Make: Lear Jet

Model: 60

Airplane Rating(s) (Check all that apply) ☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☒ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) (Check all that apply) ☒ None ☐ Airship ☐ Balloon ☒ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) (Check all that apply) ☐ None ☒ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) (Check all that apply) ☐ None ☒ Instrument Airplane ☒ Airplane Single-Engine ☐ Instrument Helicopter ☐ Airplane Multi-Engine ☐ Helicopter ☐ Gyroplane ☐ Glider ☐ Powered Lift ☐ Sport
--	---	--	---

Type Ratings

BE300
 CE 500
 DC 3
 G 1159
 LR045
 LR-60

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	7,700	800	2,200							
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

“FLIGHT CREWMEMBER 2” INFORMATION

“Flight Crewmember 2” Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

“Flight Crewmember 2” was pilot flying ☐ Yes ☐ No

“Flight Crewmember 2” Identification

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
 Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy
 Certificate Number: _____

Degree of Injury

☐ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☐ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

_____ mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

_____ mm/dd/yyyy

Flight Review Aircraft

Make: _____

Model: _____

Airplane Rating(s) (Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☐ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multi-Engine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered Lift ☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: <u>Ryan</u> City : <u>San Francisco</u> Middle Initial: _____ State: <u>CA</u> ZIP: <u>94117</u> Last Name: <u>Arroyo</u> Country: <u>USA</u> ☐ Crew ☒ Passenger ☐ Other			☒ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☒ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>DRO</u> City: <u>Durango</u> State: <u>CO</u> Country: <u>USA</u>	Time of Departure Time: <u>11:00AM</u> Time Zone: <u>MT</u>	Destination Airport ID: <u>5V5</u> City: <u>Shiprock</u> State: <u>Shiprock NM</u> Country: <u>USA</u>	Type Flight Plan Filed ☒ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☐ Yes ☐ No ☐ Unknown
--	--	---	--

Type of ATC Clearance/Service (Check all that apply)				
☒ None	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☐ VFR	☐ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)			Altitude of In-Flight Occurrence: _____ ft msl
☐ Class A	☒ Class G	☐ Military Operations Area (MOA)	☐ Special
☐ Class B	☐ Demo Area	☐ Airport Advisory Area	☐ Air Traffic Control Area
☐ Class C	☐ Warning Area	☐ Jet Training Area	☐ Unknown
☐ Class D	☐ Prohibited Area	☐ TRSA	
☐ Class E	☐ Restricted Area	☐ FAR 93	

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information (Check all that apply)	Weather Observation Facility
☐ National Weather Service ☐ Flight Service Station ☐ TV/Radio ☒ Automated Report ☒ Commercial Weather Service (DUATS) ☐ On-Board Weather	Facility ID: <u>FMN</u> Observation Time: <u>11:20</u> Time Zone: <u>Mountain time</u> Distance from Accident Site: <u>23</u> nm Direction from Accident Site: <u>52</u> degrees true
☐ Company ☐ Military ☐ Internet ☐ None ☐ Unknown	

Basic Conditions ☒ VMC ☐ IMC ☐ Unknown	Light Condition ☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown ☒ Day ☐ Night ☐ Bright Night
---	---

Sky/Lowest Cloud Condition ☒ Clear ☐ Thin Broken ☐ Few ☐ Thin Overcast ☐ Partial Obscuration ☐ Unknown ☐ Scattered	Ceiling ☒ None (Clear) ☐ Obscured ☐ Broken ☐ Indefinite ☐ Overcast ☐ Unknown	Temperature: <u>12</u> (C) or _____ (F) Dew Point: _____ (C) or _____ (F) Altimeter Setting: _____ in. Hg or _____ MB
Lowest Cloud Condition Height _____ ft agl	Ceiling Height _____ ft agl	

Wind Direction ☐ Variable -or- Direction: <u>200</u> degrees true	Wind Speed ☐ Calm ☐ Light and Variable -or- Speed: <u>4</u> kts	Wind Gusts ☒ Not Gusting -or- Speed: _____ kts	Visibility <u>unlimited</u> miles RVR: _____ feet RVV: _____ miles Density Altitude: _____ ft
--	--	--	--

Intensity of Precipitation ☐ Light ☐ Moderate ☐ Heavy ☐ N/A ☐ Unknown	Type of Precipitation (Check all that apply)	Restriction to Visibility (Check all that apply)
	☒ None ☐ Drizzle ☐ Freezing Rain ☐ Rain ☐ Ice Pellets ☐ Snow Shower ☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower ☐ Hail ☐ Snow Grains ☐ Freezing Drizzle ☐ Rain Showers ☐ Ice Crystals	☒ None ☐ Fog ☐ Blowing Dust ☐ Ground Fog ☐ Blowing Sand ☐ Haze ☐ Blowing Snow ☐ Ice Fog ☐ Blowing Spray ☐ Smoke ☐ Dust ☐ Unknown

Icing Forecast	Icing Actual	Turbulence																																						
<table border="0"> <tr> <th>Amount</th> <th>Type</th> </tr> <tr> <td>☒ None</td> <td>☐ N/A</td> </tr> <tr> <td>☐ Trace</td> <td>☐ Rime</td> </tr> <tr> <td>☐ Light</td> <td>☐ Clear</td> </tr> <tr> <td>☐ Moderate</td> <td>☐ Mixed</td> </tr> <tr> <td>☐ Severe</td> <td>☐ Unknown</td> </tr> <tr> <td>☐ Unknown</td> <td></td> </tr> </table>	Amount	Type	☒ None	☐ N/A	☐ Trace	☐ Rime	☐ Light	☐ Clear	☐ Moderate	☐ Mixed	☐ Severe	☐ Unknown	☐ Unknown		<table border="0"> <tr> <th>Amount</th> <th>Type</th> </tr> <tr> <td>☒ None</td> <td>☐ N/A</td> </tr> <tr> <td>☐ Trace</td> <td>☐ Rime</td> </tr> <tr> <td>☐ Light</td> <td>☐ Clear</td> </tr> <tr> <td>☐ Moderate</td> <td>☐ Mixed</td> </tr> <tr> <td>☐ Severe</td> <td>☐ Unknown</td> </tr> <tr> <td>☐ Unknown</td> <td></td> </tr> </table>	Amount	Type	☒ None	☐ N/A	☐ Trace	☐ Rime	☐ Light	☐ Clear	☐ Moderate	☐ Mixed	☐ Severe	☐ Unknown	☐ Unknown		<table border="0"> <tr> <th>Type</th> <th>Severity</th> </tr> <tr> <td>☒ None</td> <td>☐ Light</td> </tr> <tr> <td>☐ Clear Air</td> <td>☐ Moderate</td> </tr> <tr> <td>☐ Terrain-Induced</td> <td>☐ Severe</td> </tr> <tr> <td>☐ Convective Turbulence</td> <td>☐ Extreme</td> </tr> </table>	Type	Severity	☒ None	☐ Light	☐ Clear Air	☐ Moderate	☐ Terrain-Induced	☐ Severe	☐ Convective Turbulence	☐ Extreme
Amount	Type																																							
☒ None	☐ N/A																																							
☐ Trace	☐ Rime																																							
☐ Light	☐ Clear																																							
☐ Moderate	☐ Mixed																																							
☐ Severe	☐ Unknown																																							
☐ Unknown																																								
Amount	Type																																							
☒ None	☐ N/A																																							
☐ Trace	☐ Rime																																							
☐ Light	☐ Clear																																							
☐ Moderate	☐ Mixed																																							
☐ Severe	☐ Unknown																																							
☐ Unknown																																								
Type	Severity																																							
☒ None	☐ Light																																							
☐ Clear Air	☐ Moderate																																							
☐ Terrain-Induced	☐ Severe																																							
☐ Convective Turbulence	☐ Extreme																																							

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

no NOTAMs

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

the aircraft was on its back, tail in direction of movement, prop strike, fuselage major damage.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

We arrived at departure airport KDRO at 10:30. Preflighted the airplane, no services, 37 Gallons of fuel on board, evenly divided between the left and the right tank. Uneventful take off at 11 AM.

Joe Tumminaro flew directly from KDRO to 5V5, Shiprock airport. Enroute picked up the Farmington KFMN ATIS at approximately 11:20. Indicated winds at 200 degrees at 4 knots which was consistent with information obtained during preflight planning from National Weather Service. Joe decided runway 20 due to wind direction.

Joe passed over the airport examining the runway and segmented circle. No issues observed on the runway and left traffic for runway 20 was indicated. Maneuvered for a 45 degree entry to left downwind runway 20. Notified local traffic of our approach (no local traffic). Proceeded on normal left-hand pattern runway 20.

30% of flaps upon landing. Touch down in 3 point configuration at approximately 50 miles per hour. Soon after touching down, there was a left quartering tailwind gust that pushed the airplane off the runway to the right. Joe was unable to correct it back to a straight path. The airplane entered a ditch very close to the right- side runway edge. It rolled forward and upside down, coming to rest on the tail. One wheel was torn off, one wheel remained intact. Propeller was bent back over the engine cowling.

After impact, Joe Tumminaro was unable to move, so he stayed upside down in his harness and seat belt. He assessed the situation, determining if the passenger was hurt. Passenger was not, so Joe instructed him to turn off the fuel, turn off the mags, turn off the master. Joe estimated there was about 15 gallon per side of remaining fuel.

Joe then asked the passenger to get out and told the passenger Joe was unable to move. Joe instructed passenger to call 911 and explained the crash had happened and there was one person injured.

Joe then asked the passenger to pull the pins on both doors so it would help clear the path for the emergency responders. While waiting for the paramedics, the passenger lowered the seat Joe was in and pulled it back - again under Joe's direct and to aid in getting Joe out of the plane.

Paramedics arrived quickly (~10 minutes), While waiting Joe had no feeling from the neck down. The paramedics got Joe out of the plane, onto a gurney, ambulance, helicopter, then transported to San Juan Regional Medical Center in Farmington New Mexico. Joe's injuries required a higher level of care, so was transported 1 week later to Acute Rehab Center of Swedish Medical Center in Englewood CO (Denver metro area).

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

No recommendations

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☐ Yes ☒ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

37 Gallons**Fuel Type**☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive**Other Services, if Any, Prior to Departure**

no

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☒ Yes ☐ No**Method of Exit** – Describe how the occupants exited and how many occupants evacuated each location

Passenger exited normally. Then, under instruction of Joe Tumminaro (pilot) he removed the pins on the doors. Joe Tumminaro could not move or feel anything below his neck. Therefore he needed to be evacuated by the paramedics.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)**Aircraft Registration Number**

Manufacturer: _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

04/10/2016

mm/dd/yyyy

Name of Pilot/Operator: Joseph Tumminaro

Signature: _____

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

CEN16LA138

Reviewed by NTSB Regional Office

NTSB, Central Region

Name of Investigator

Andrew Todd Fox

Date Report Received

11 April 2016