



Photo 1 – Accident site as approached from the south



Photo 2 – Fuselage wreckage



Photo 3 – Left wing wreckage



Photo 4 – Right wing wreckage



Photo 5 – Empennage wreckage



Photo 6 – Engine wreckage



Photo 7 – Vertical stabilizer attachment hardware